




บริษัท มากูส จำกัด 25/8 หมู่ 12 ต.บึงคำพร้อย อ.ลำลูกกา จ.ปทุมธานี 12150 โทร:(02)152-7244-5 โทรสาร:(02)152-7248

Makusu Co.,Ltd. 25/8 Moo 12 T.Buengkamproy A.Lamlukka, Pathumtani 12150 Tel : (02)152-7244-5 Fax:(02)152-7248

SCREW FINAL INSPECTION RECORD

DATE : 29/3/2021 PART NAME : 1524-0001-9
 LOT NO: PART NO.: JT+BT M3x10 (CR3)
 CUSTOMER : REF.:
 MATERIAL : QUANTITY : 1,000 pcs / Bag DELIVERY QTY pcs

INSPECTION RECORD



INSPECTION ITEMS	STD/TOLERANCE	EQUIPMENT		1	2	3	4	5	6	7	8	RESULT
		Device	No.									
Head Dia	5.00-5.50	QV	01	5.40	5.46	5.42	5.42	5.46				
Threading Length	9.80-10.20	QV	01	9.55								
Thread Dia	2.90-3.00	QV	01	2.96	2.96	2.96	2.97	2.96				
Length	9.20-10.00	QV	01	9.72	10	10	10	10				
Diameter	2.00-2.20	QV	01	2.14	2.14	2.14	2.14	2.14				
Plating	Sn	VS	-	/	/	/	/	/				
Appearance	M6.0 x 1.0	VS	-									

Legend of equipment used :

QV = Vernier QQ = Q Gauge QT = Dial Indicating Torque QPJ = Profile Projector
 QM = Micro Major QG = Ring Gauge VS = Visual QMH = Micro Hardness
 QH = Micro High QP = Pin Gauge QMT = Micro Major (THR) Other.....

REMARK :

RESULT : () ACCEPTABLE () REJECT

Q.A. LEADER..... Panida

Q.C. LEADER..... Jenwarin

INSPECTOR..... Jenwarin

QC 07/VERSION 2